L Number	Hits	Search Text	DB	Time stamp
1	0	("((test or probe) near Pad) and aluminum and copper").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT;	2003/06/01 20:01
2	291	((test or probe) near Pad) and aluminum and copper	IBM_TDB USPAT; US-PGPUB; EPO; JPO;	2003/06/01 20:01
3	199	(((test or probe) near Pad) and aluminum and copper) and wire	DERWENT; IBM_TDB USPAT; US-PGPUB; EPO; JPO;	2003/06/01 20:02
4	51	(((test or probe) near Pad) and aluminum and copper) and ((wire adj bond) or wirebond)	DERWENT; IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT;	2003/06/01 20:18
5	274	(test with ((wire adj bond) or wirebond))	IBM_TDB USPAT; US-PGPUB; EPO; JPO;	2003/06/01 20:06
6	196	((test with ((wire adj bond) or wirebond))) and (chip or die)	DERWENT; IBM_TDB USPAT; US-PGPUB; EPO; JPO;	2003/06/01 20:07
7	151	(((test with ((wire adj bond) or wirebond))) and (chip or die)) and pad	DERWENT; IBM_TDB USPAT; US-PGPUB; EPO; JPO;	2003/06/01 20:18
8	33	257/48.ccls. and ((wire adj bond) or wirebond)	DERWENT; IBM_TDB USPAT; US-PGPUB; EPO; JPO;	2003/06/01 20:19
9	28	(damage near active) and ((wire adj bond) or wirebond)	DERWENT; IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT;	2003/06/01 20:24
10	36	(damage near pad) and ((wire adj bond) or wirebond)	IBM_TDB USPAT; US-PGPUB; EPO; JPO;	2003/06/01 20:25
11	1	<pre>(prevent near active) and ((wire adj bond) or wirebond)</pre>	DERWENT; IBM_TDB USPAT; US-PGPUB; EPO; JPO;	2003/06/01 20:25
12	188	257/784.ccls. and ((wire adj bond) or wirebond)	DERWENT; IBM_TDB USPAT; US-PGPUB; EPO; JPO;	2003/06/01 20:27
13	101	257/784.ccls. and offset	DERWENT; IBM_TDB USPAT; US-PGPUB; EPO; JPO;	2003/06/01
14	811	257/784.ccls. and pad	DERWENT; IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT;	2003/06/01 20:27

Search History

6/1/03 8:48:13 PM Page 1

15	680	(257/784.ccls. and pad) and wire	USPAT;	2003/06/01
		_	US-PGPUB;	20:27
			EPO; JPO;	
			DERWENT;	
			IBM TDB	

Search History 6/1/03 8:48:13 PM

Page 2